

Material Safety Data Sheet May be used to comply with OSHA's Hazard Communication Standard, 29 CFR 1910.1200. Standard must be consulted for specific requirements.

U.S. Department of Labor Occupational Safety and Health Administration (Non-Mandatory Form) Form approved OMB No. 1218-0072

IDENTITY (As Used on Label and List) P101,P107,P110 BRAZING PAST	Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that						
Section I							
Manufacturer's Name		Emergency Telephone Number					
KROHN INDUSTRIES, INC.		(201) 933-9696					
Address (Number, Street, City, State, and ZIP	Code)	Telephone Number for Information					
303 VETERANS BOULEVARD		(201) 933–9696  Date Prepared					
CARLSTADT, NEW JERSEY 07	AUGUST 20, 2014. (REVISION DATE) Signature of Preparer (optional)						
•							
Section II — Hazardous Ingredients	s/Identity Information		• .				
Hazardous Components (Specific Chemical k	OSHA PEL AC	GIH TLV	Other Limits Recommended	% (optiona			
*****	CAS#10043-35-3		N.A.				
BORIC ACID POTASSIUM TETRABORATE	CAS#1332-77-0		2.5mg/m3		<del></del>		
POTASSIUM FLUORDIE	CAS#7789-23-3						
			•				
				<del> </del>			
				<del> </del>	*		
					· · · · · · · · · · · · · · · · · · ·		
			· · · · · · · · · · · · · · · · · · ·				
				*			
	•			d			
Section III — Physical/Chemical Ci	naracteristics						
Boiling Point		Specify Gravity (H <sub>2</sub> O = 1)					
	N.A.				N.A.		
Vapor Pressure (mm Hg.)		Melting Point			33. 4		
	N.A.		· · ·		N.A.		
Vapor Density (AIR = 1)	N.A.	Evaporation Rate (Butyl Acetate = 1)			N.A.		
Solubility in Water		1, , , , , , , , , , , , , , , , , , ,			1		
Nil							
Appearance and Odor Dark grey, bloom	ack or brown paste	e when mixed wit	h alloy.N	No odor.			
Section IV — Fire and Explosion H	azard Data						
Flash Point (Method Used) N/A		Flammable Limits - N/A		LEL	UEL		
Extinguishing Media		1			····		
Dry chemical, CO, foam	, waterfog, sand	earth.					
Special Fire Fighting Procedures - Water spray is an unsui	table extinations	ng agant Timb	fightene	should use			
self-contained breathin	g apparatus to pr	otect against so	oke inha	lation			
Unusual Fire and Explosion Hazards None					<del></del>		
***							

Stable   X   Stable at room temperature.	Section V—	- Reactivity E	)ata				54.
**Stable at recont temperature.**  **Compassibility (Matarials to Accid) Flame, heat (250°P Many), and strong exiditing agents.**  **Instance of the strong of the strong of the strong oxiditing agents.**  **Instance of the strong of the strong oxiditing agents.**  **Instance of the strong of the strong oxiditing agents.**  **Instance of the strong of the strong oxiditing agents.**  **Instance of the strong of the strong oxiditing agents.**  **Instance oxiditing oxiditing agents.**  **Instance oxiditing oxiditing oxiditing agents.**  **Instance oxiditing oxiditing oxiditing agents.**  **Instance oxiditing oxiditing oxiditing oxiditing agents.**  **Instance oxiditing oxiditing oxiditing oxiditing agents.**  **Instance oxiditing oxiditing oxiditing oxiditing oxiditing oxiditing oxiditing oxiditing.**  **Instance oxiditing oxiditing oxiditing oxiditing oxiditing oxiditing oxiditing oxiditing.**  **Instance oxiditing	Stability	Unstable		Conditions to Avoid			<del>/</del>
connectability (Meterals to Acad Flame, heat (250°F Max), and strong oxidizing agents.  **stratous Decomposition or Bygoduck Flouride fumes of gas, pro pas on heating during brazing. Also, a continuous and continuous and carbon individe.  **Mey Good**  **Wey Good**  **Wey No Counter of Sention**  **Section VI — Health Hazard Data**  **Conditions to Acad Conditions to Be Taken in Handing and Storing Conditions to Acad		Stable	х	Stable at room temper	eture.		
Section VI — Health Hazard Data  Conditions to Avoid  Conditions to Avoid Contact with Skin or eyes. Avoid high  Temperature. Wear rubber gloves during spill clean up.  Vasid Disposal Method Consider possible reclaim value. Sorap alloy can be disposed of through a licent Conditions to Be Taken in Case Masterial is Released or Spiled  Avoid contact with skin or eyes. Avoid high  Temperature. Wear rubber gloves during spill clean up.  Vasid Disposal Method Consider possible reclaim value. Sorap alloy can be disposed of through a licent Condition and the Avoid Contact with skin or eyes. Avoid high  Temperature in Case Masterial is Released or Spiled  Avoid contact with skin or eyes. Avoid high  Temperature in Case Masterial is Released or Spiled  Avoid contact with skin or eyes. Avoid high  Temperature in Case Masterial is Released or Spiled  Avoid contact with skin or eyes. Avoid high  Temperature in Case Masterial is Released or Spiled  Avoid contact with skin or eyes and the Avoid	Incompatibility (	(Materials to Avo		ame. heat (250°F Max).	and stron	g oxidizing agents	````
Section VI — Health Hazard Data  Convels; of Entry:   Inhabition?   Y   Skin?   Y   Ingestion?   Y    Section VI — Health Hazard Data  Convels; of Entry:   Inhabition?   Y   Skin?   Y   Ingestion?   Y    Section VI — Health Hazard Data  Convels; of Entry:   Inhabition?   Y   Skin?   Y   Ingestion?   Y    Section VI — Health Hazard Skin. Frolonged exposure may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause characterized product the product of the product of the product of the mose throat, and respiratory tract; dough, notes bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Precautions for Safe Handling and Use  Section VII — Safe Safe Safe Safe Safe Safe Safe	Hazardous Dec	omposition or By	produc	s Flouride fumes or gas	BET gas	on heating during brazing.	Also,
Section VI — Health Hezard Data  Toute(s) of Entry:  Inhalation? Y Skin? Y Ingustion? Y  Skin? Y Ingustion? Y  Skin irritation particularly on abraded skin. Prolonged exposure may cause dermatitis. Some components of thi product are potentially toxic if ingested, and may cause insuses, vomiting, diarrhea, abdominal pain, gastrointestinal irritation, convulsions, tachycardia, cramps, and central nervous system depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; Sough, mose bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary deema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaire pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  With water for at least fifteen minutes. Seek medical assistance if necessary.  Section VII — Precautions for Safe Handling and Use  Response to Be Taken in Case Material is Reseased or Spilled Avoid contact with skin or eyes. Avoid high  temperature. Wear rubber gloves during spill clean up.  Waste Disposal Method Consider possible reclaim value. Sorap alloy can be disposed of through a licential staken to Handling and Storing  Avoid contact with skin or eyes. Avoid high  temperature. Wear rubber gloves during spill clean up.  Waste Disposal Method Consider possible reclaim value. Sorap alloy can be disposed of through a licential staken throading and Storing  Avoid contact with skin or eyes. Avoid high  temperature in the staken of Handling and Storing  Avoid contact with skin or eyes. Avoid high  temperature in the staken of Handling and Storing  Avoid contact with skin or eyes. Avoid high  temperature in the staken of Handling and Storing  Avoid contact with skin or eyes. Avoid high  temperature in the staken of Handling and Storing  Avoid contact with skin or eyes. Avoid high  The Precautions Tingestion—If subject is conscious, induce vomiting. Seek immediate medical  Inhalation— Remove subject from	Hazardous	May Occur	See	Conditions to Avoid	xide and	Carbon Dioxide.	
Section VI — Health Hazard Data  Notices of Entry I rhelation? Y Skin? Y Ingestion? Y  Seath Hazards (Acute and Chronic) Eye irritation, or eye injury upon prolonged contact. Skin irritation particularly on abraded skin. Prolonged exposure may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause: nauses, womiting, diarrhea, abdominal pain, gastrointestinal irritation, convulsions, tachycardia, cramps, and central nervous system depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; 60ugh, nose bleeds, nausea, womiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary furcition, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  **Management of the state of mobility in joints.**  **Imagency and First Aid Procedures**  **Proceedings of the state	Polymerization	Willi-Not Occur	-	-			
inhalation? Y Skin? Y Ingestion? Y ingestion? Y ingestion? Y ingestion? Y issum Hazards (Acute and Chronic) Eye irritation, or eye injury upon prolonged contact. Skin irritation particularly on abraded skin. Prolonged exposure may cause dermatitis. Some components of this product are potentially toxic if ingested, and may cause insuses, womiting, diarrhea, abdominal pain, gastrointestinal irritation, convulsions, tachycardia, cramps, and central nervous system depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; Sough, mose bleeds, nauses, womiting, chest tightness, chills, fever, tearing, pneumonits, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaire pulmonary furction, and fluorosis(a fisease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  **The Procedures** Skin- Remove contaminated clothing. Flush affected areas with with water for at least fifteen minutes. Seek medical assistance if necessary.  **Section VII — Precautions for Safe Handling and Use**  **Section VII — Precautions for Safe Handling and Use**  **Section VII — Precautions for Safe Handling and Use**  **Section VII — Precautions for Safe Handling and Use**  **Section VII — Precautions for Safe Handling and Use**  **Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  **Veste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licer of waste disposal company, in accordance with Pederal, State and Local regulations. The disposal for collected times (see section VIII) from the exhaust ventilation system must be considered assistance. Rever attempt to give anything by mouth to an unconscious or covalsive person. Inhalation— Semove subject from area administer oxygen. seek medical attention.  **Described Counties of Counties (Special, Type)*  **The Procedure Counties of Countie	Section VI -	⊥ – Health Haz		ata	····		· · · · · · · · · · · · · · · · · · ·
particularly on abraded skin. Prolonged exposure may cause dermatitis. Some components of thi product are potentially toxic if ingested, and may cause nause dermatitis. Some components of thi product are potentially toxic if ingested, and may cause nause, vomiting, diarrhea, abdominal pain, gastrointestinal irritation, convulsions, tachycardia, cramps, and central nervous system depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; dough, mose bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary deems. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaire pulmonary function, and fluorosis(a fisease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  The production of the control of the con				tlan? Skin?	v	Ingestion? v	
product are potentially toxic if ingested, and may cause:nauses, vomiting, diarrhea, abdominal pain, gastrointestinal irritation, convulsions, tachycardia, cramps, and central nervous system depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; dough, mose bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  **Emergency and First Aid Procedures**  **Emergency and First Aid Procedures**  **Skin- Remove contaminated clothing. Flush affected areas with with water for at least fifteen minutes. Seek medical assistance if necessary.  **Section VII — Precautions for Safe Handling and Use  **Resise Dispossi Method Consider possible reclaim value. Scrap alloy can be disposed of through a licer of waste disposal company, in accordance with rederal, State and Local regulations. The dispose of collected fumes (see section VIII) from the exhaust ventilation system must be considered also.  **Procedures**  *	Health Hazards	(Acute and Chri	onic) <sub>E</sub>	Till demoderation on any d		I	
product are potentially toxic if ingested, and may cause: nausea, vomiting, diarrhea, abdominal pain, gastrointestinal irritation, convulsions, tachycardia, cramps, and central nervous system depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; dough, mose bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  "Moreover and Procedures of Moreover and Procedures and Procedures of Moreover Subject from area administer oxygen. Seek medical attention.  **Moreover Procedures of Each Procedure of Experiency Protection (Specify, Type)**  **Moreover Procedures of Each Procedure of Experiency Protection (Specify, Type)**  **Moreover Department of Procedure of Experiency Protection (Specify, Type)**  **Moreover Department of Experiency Procedure of Experiency Protection (Specify, Type)**  **Moreover Department of Experiency Procedure of Experiency Protection (Specify, Type)**  **Moreover Department of Experiency Procedure of Experiency Protection (Specify, Type)**  **Moreover Department of Experiency Procedure of Experien	particula	rly on abra	aded	skin. Prolonged exposur	<u>injury upo</u> re may car	on prolonged contact. Skin	<u>irritati</u> on
pain, gastrointestinal irritation, convulsions, tachycardia, cramps, and central nervous system depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; dough, mose bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  Margency and First Aid Procedures Skin-Remove contaminated clothing. Flush affected areas with with water for at least fifteen minutes. Seek medical assistance if necessary.  Medical VIII — Precautions for Safe Handling and Use  Messey to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Waste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent of the waste disposal company, in accordance with Federal, State and Local regulations. The dispose of collected Tunes (see section VIII) from the exhaust ventilation system must be considered recoulons to be Taken in Handling and Storing also.  When Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covalidive person. Inhalation—Remove subject from area administer oxygen, seek medical attention.  Method Constitution (Specify, Type)  Mentilation   Local Exhaust Air flow to produce velocity of Species Natural (min): 10,000 cu.ft./brazer & agass)   Collective Mini./orazer (see footnote).   Side shields—Nitter lenses shade 2 or 4.    Mormal clothing for torch brazing. (Avoid flammable fabrics.)							
depression. Acute exposure: Irritation to the nose, throat, and respiratory tract; Gough, mose bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  Emergency and First Aid Procedures Skin- Remove contaminated clothing. Flush affected areas with myth water for at least fifteen minutes. Seek medical assistance if necessary.  Section VII — Precautions for Safe Handling and Use  Steps to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Vaste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent and waste disposal company, in accordance with Federel, State and Local regulations. The disposal disposal company, in accordance with Federel, State and Local regulations. The disposa of scillected funes, (see section VIII) from the exhaust ventilation system must be considered recaulions to be Taken in Handling and Storng assistance. Never attempt to give anything by mouth to an unconscious or covulsive percental consistence. Never attempt to give anything by mouth to an unconscious or covulsive percentages in the state of the section VIII — Control Measures  Respiratory Protection (Specify, Type)  Removed the protection (Specify Type)  Removed the protec			<del>-</del>		·		
mose bleeds, nausea, vomiting, chest tightness, chills, fever, tearing, pneumonitis, and pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  Imergency and First Aid Procedures Skin- Remove contaminated clothing. Flush affected areas with with water for at least fifteen minutes. Seek medical assistance if necessary.  Section VII — Precautions for Safe Handling and Use  Steps to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Waste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent disposal company, in accordance with Federal, State and Local regulations. The disposal facility clean in Heading and Storing assistance. Never attempt to give anything by mouth to an unconscious or covuleive person. Inhalation Remove subject from area administer oxygen. seek medical attention.  Section VIII — Control Measures  Replication   Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furned procedure)   Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furned procedure)   Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furned procedure)   Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (Local Ex				·			
pulmonary edema. Chronic exposure: Abdominal pain and cramps, liver and kidney damage, impaired pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  Imergency and First Aid Procedures Sidn-Remove contaminated clothing. Flush affected areas with with water for at least fifteen minutes. Seek medical assistance if necessary.  Section VII — Precautions for Safe Handling and Use  Reps to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Waste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent of waste disposal company, in accordance with Federal, State and Local regulations. The disposal foculated firmes (see section VIII) from the exhaust ventilation system must be considered also.  Other Precautions to Be Taken in Handling and Storing also in the exhaust ventilation system must be considered also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covuleive person. Inhalation—Remove subject from area administer oxygen, seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Measure) in brazing zone.  Experience of the protection of the protective Gloves and the protective Gloves are safety spectageles with side shields—Titler lenses shade #7 or #4.  Where Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)						<del>*************************************</del>	<del></del>
pulmonary function, and fluorosis(a disease characterized by mottled teeth, osteosclerosis, and pain and loss of mobility in joints).  Imergency and First Aid Procedures Skin- Remove contaminated clothing. Flush affected areas with with water for at least fifteen minutes. Seek medical assistance if necessary.  Section VII — Precautions for Safe Handling and Use  Reps to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Vaste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent of waste disposal company, in accordance with Federal, State and Local regulations. The disposal collected furnes (see section VIII) from the exhaust ventilation system must be considered also.  Other Procautions to Be Taken in Handling and Storing also in the analysis of collected furnes (see section VIII) from the exhaust ventilation system must be considered also.  Other Procautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhalation—Remove subject from area administer oxygen, seek medical attention.  Bection VIII — Control Measures  Respiratory Protection (Specify, Type)  Respiratory Protection (Specify, Type)  Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Measures) and Special Specia							
and pain and loss of mobility in joints).  Imergency and First Aid Procedures Skin- Remove contaminated clothing. Flush affected areas with with water for at least fifteen minutes. Seek medical assistance if necessary.  Section VII — Precautions for Safe Handling and Use  Reps to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Vaste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent of waste disposal company, in accordance with Federal, State and Local regulations. The dispose of collected funes (see section VIII) from the exhaust ventilation system must be considered receptions to Be Taken in Handling and Storing also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhalation—Remove subject from area administer oxygen, seek medical attention.  Section VIII — Control Measures  The Control Measures  The Control Measures  The Protection (Specify, Type)  The Control Measures  The Protection (Specify Type)  The Protection Gloves Leather Welding gloves.  Ever Protection Flattic frame safety spectacles with side shields—Itter lenses shade #; or #4.  The Protective Clothing or Equipment Roomal clothing for torch brazing. (Avoid flammable fabrics.)	pulmonary	edema. Chi	ronic	exposure: Abdominal pa	ain and cr	ramps,liver and kidney dam	<u>age, impa</u> ire
with water for at least fifteen minutes. Seek medical assistance if necessary.  Section VII — Precautions for Safe Handling and Use  Steps to Se Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high  temperature. Wear rubber gloves during spill clean up.  Vaste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licer of waste disposal company, in accordance with Federal, State and local regulations. The dispose of collected tumes (see section VIII) from the exhaust ventilation system must be considered recently be a section viii) from the exhaust ventilation system must be considered recently be a section viii) from the exhaust ventilation system must be considered recently be a section viii) from the exhaust ventilation system must be considered recently be a section viii) from the exhaust ventilation system must be considered recently be a section viii) from a seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhalation seemove subject from area administer oxygen, seek medical attention.  Section VIII — Control Measures  Section VIII — Control Measures  Seek immediate medical attention.  Section VIII — Control Measures  Section	pulmonary	function,	and	fluorosis(a disease cha	ıracterize	ed by mottled teeth, osteon	sclerosis,
Section VII — Precautions for Safe Handling and Use  Steps to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Veste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent of waste disposal company, in accordance with Federal, State and Local regulations. The disposal federal considered furnes (see section VIII) from the exhaust ventilation system must be considered recautions to Be Taken in Handling and Storing also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhalation—Remove subject from area administer oxygen, seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (See Special Specify) of Mechanic (Specify) or #4.  Where Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	and pain	and loss of	f mot	oility in joints).			
Section VII — Precautions for Safe Handling and Use  Steps to Be Taken in Case Material is Released or Spilled Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Veste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent of waste disposal company, in accordance with Federal, State and Local regulations. The disposal federal considered furnes (see section VIII) from the exhaust ventilation system must be considered recautions to Be Taken in Handling and Storing also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhalation—Remove subject from area administer oxygen, seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (For furnes Mechanic (Specify, Type)  Rentilation Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer (See Special Specify) of Mechanic (Specify) or #4.  Where Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	Emergency and	First Aid Proced	ures	Skin- Remove contaminat	ed clothi	ng. Flush affected ar	eas with
Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Waste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licented waste disposal company, in accordance with Federal, State and local regulations. The disposal collected furnes (see section VIII) from the exhaust ventilation system must be considered also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhelation—Remove subject from area administer oxygen, seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  entilation—Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For furnes Mechania (Sepcify, Type)  entilation—Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For furnes Mechania (Sepcify, Type)  Every Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	with wate	er for at 1	.east	fifteen minutes. Seek	medical a	ssistance if necessary.	
Avoid contact with skin or eyes. Avoid high temperature. Wear rubber gloves during spill clean up.  Waste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licent of waste disposal company, in accordance with Federal, State and Local regulations. The disposal foculected furnes (see section VIII) from the exhaust ventilation system must be considered also.  The Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person.  Inhelation—Remove subject from area administer oxygen, seek medical attention.  Section VIII—Control Measures  Respiratory Protection (Specify, Type)  Tentilation—Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer  (For furnes Measures Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer  (For furnes Measures Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer  (For furnes Measures Measur	Section VII -	— Precaution	s for	Safe Handling and Use			
Waste Disposal Method Consider possible reclaim value. Scrap alloy can be disposed of through a licented waste disposal company, in accordance with Federal, State and Local regulations. The disposal of collected fumes (see section VIII) from the exhaust ventilation system must be considered recautions to Be Taken in Handling and Storing  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhalation—Remove subject from area administer oxygen. seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  Gentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For fumes Mechanical General Min./orazer(see footnote)).  Gentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For fumes Mechanical General Min./orazer(see footnote)).  Gentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For fumes Mechanical General Min./orazer(see footnote)).  Gentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For fumes Mechanical General Min./orazer(see footnote)).  Gentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For fumes Mechanical General Min./orazer(see footnote)).  Gentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For fumes Mechanical General Min./orazer(see footnote)).  Gentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (min):	Steps to Be Ta	ken in Case Mat	erial is	Released or Spilled Avoid c	ontact wi	th skin or eyes. Avoid hi	gh
waste disposal company, in accordance with Federal, State and Local regulations. The disposal collected furnes (see section VIII) from the exhaust ventilation system must be considered also.  Other Precautions to Be Taken in Handling and Storing also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person.  Inhelation—Remove subject from area administer oxygen. seek medical attention.  Gection VIII — Control Measures  Respiratory Protection (Specify, Type)  Remail (Septeral) ft./min in brazing zone.  Remove attempt to give anything by mouth to an unconscious or covulsive person.  Inhelation—Remove subject from area administer oxygen. seek medical attention.  Respiratory Protection (Specify, Type)  Remail (Septeral) ft./min in brazing zone.  Report of times (Septeral) ft./min in brazing zone.  Regases) 2.000 cu.ft./brazer(see footnote).  Report of times after the safety spectacles with side shields—filter lenses shade #2 or #4.  Report of times of Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	temperatu	re. Wear	rubb				
waste disposal company, in accordance with Federal, State and Local regulations. The disposal collected furnes (see section VIII) from the exhaust ventilation system must be considered also.  Other Precautions to Be Taken in Handling and Storing also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person.  Inhelation—Remove subject from area administer oxygen. seek medical attention.  Gection VIII — Control Measures  Respiratory Protection (Specify, Type)  Remail (Septeral) ft./min in brazing zone.  Remove attempt to give anything by mouth to an unconscious or covulsive person.  Inhelation—Remove subject from area administer oxygen. seek medical attention.  Respiratory Protection (Specify, Type)  Remail (Septeral) ft./min in brazing zone.  Report of times (Septeral) ft./min in brazing zone.  Regases) 2.000 cu.ft./brazer(see footnote).  Report of times after the safety spectacles with side shields—filter lenses shade #2 or #4.  Report of times of Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)							
waste disposal company, in accordance with Federal, State and Local regulations. The disposal collected furnes (see section VIII) from the exhaust ventilation system must be considered also.  Other Precautions to Be Taken in Handling and Storing also.  Other Precautions Trigestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person.  Inhelation—Remove subject from area administer oxygen, seek medical attention.  Gection VIII — Control Measures  Respiratory Protection (Specify, Type)  Remail (Septeral) ft./min in brazing zone.  Remove Subject from area administer oxygen. Seek medical attention.  Geografication Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For furnes Mechanical (Septeral) min./brazer(see footnote).  Remove Subject from area administer oxygen. Seek medical attention.  Geografication Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For furnes Mechanical (Septeral) min./brazer (see footnote).  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area administer oxygen. Seek medical attention.  Geografication (Specify, Type)  Remove Subject from area adm	Waste Disposal	Method Consi	der	possible reclaim value.	Serap al	lov can be disposed of thr	ough a licer
Also.  Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person.  Inhelation—Remove subject from area administer oxygen, seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  Tentilation   Local Exhaust Air flow to produce velocity of Special Natural(min): 10,000 cu.ft./brazer  (For fumes   Mechanical (Specify, min in brazing zone.   Other 16ft. ceiling no obstructions.   Every Protective Gloves   Every Protection Plastic frame safety spectacles with side shields—filter lenses shade #3 or #4.  Other Protective Clothing or Equipment   Normal clothing for torch brazing. (Avoid flammable fabrics.)	ed waste	disposal co	mpan	y,in accordance with Fe	deral, Sta	ate and Local regulations.	The disposa
Other Precautions Ingestion—If subject is conscious, induce vomiting. Seek immediate medical assistance. Never attempt to give anything by mouth to an unconscious or covulsive person. Inhalation—Remove subject from area administer oxygen, seek medical attention.  Gection VIII — Control Measures  Respiratory Protection (Specify, Type)  For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Mechanical (Seperal), min in brazing zone.  (For fumes   General (Seperal), min in brazing zone.  (Seperal (Seperal), control Measures   Control (Seperal), min in brazing zone.  (For fumes   Seperal (Seperal), min in brazing zone.  (Seperal (Seperal), control (Seperal), min in brazing zone.  (Seperal (Seperal), min in brazing zone.	of collect Precautions to I	ted fumes ( Be Taken in Han	see dling a	<u>section VIII) from the :</u> nd Storing	exhaust v	entilation system must be	
assistance. Never attempt to give anything by mouth to an unconscious or covulsive person.  Inhalation—Remove subject from area administer oxygen. seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  Rentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air f	<del></del>						arso.
assistance. Never attempt to give anything by mouth to an unconscious or covulsive person.  Inhalation—Remove subject from area administer oxygen. seek medical attention.  Section VIII — Control Measures  Respiratory Protection (Specify, Type)  Rentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes   Local Exhaust Air f	Other Precautio	ns Indestic	m_Tf	subject is conscious.i	nduce vom	iting. Seek immediate medi	cal
Inhelation Remove subject from area administer oxygen, seek medical attention.  Gection VIII — Control Measures  Respiratory Protection (Specify, Type)  Rentilation   Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer  (For fumes Mechanica (General), whin in brazing zone.  Regases)   2,000 cu.ft./min./brazer(see footnote).  Respiratory Protective Gloves   Control of Special Natural (min): 10,000 cu.ft./brazer  (For fumes Mechanica (General), whin in brazing zone.  Regases)   2,000 cu.ft./min./brazer(see footnote).  Respiratory Protective Gloves   Control of Special Natural (min): 10,000 cu.ft./brazer  (For fumes Mechanica (General), which is brazing to the protection Plastic frame safety spectacles with side shields-filter lenses shade #3 or #4.  Other Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	assistano	e. Never a	ttem	ot to give anything by	mouth to	an unconscious or covulsiv	<del>c person</del> .
retilation Local Exhaust Air flow to produce velocity of Special Natural (min): 10,000 cu.ft./brazer (For fumes Nechanical General). Other 16ft. ceiling no obstructions.  Tother Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	_Inhalatio	n-Remove	subj	ect from area administe	r oxygen.	seek medical attention.	
(For fumes Mechanical General) in brazing zone.  (Other 16ft. ceiling no obstructions.  (For fumes Mechanical General) in brazing zone.  (Other 16ft. ceiling no obstructions.  (For fumes Mechanical General) in brazing zone.  (For fumes Mechanical General) in brazing zone.  (Other 16ft. ceiling no obstructions.  (For fumes Mechanical General) in brazing zone.  (For fumes Mechanical General) in brazing zone.  (Other 16ft. ceiling no obstructions.  (For fumes Mechanical General) in brazing in brazing in the formation in brazing zone.  (Other 16ft. ceiling no obstructions.  (For fumes Mechanical General) in brazing zone.  (For f	Section VIII	— Control M	easur	es			
(FOR lumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Ceneral Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Min./brazer(see footnote). Other 16ft. ceiling no obstructions.  (For fumes Mechanical Min./brazer(see footnote). Other 16ft. ceiling no obs	Respiratory Pro						
(FOR lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Other 16ft. ceiling no obstructions.  (For lumes Mechanical General Min. / Orazer (see footnote). Orazer (see footnote).  (For lumes Min. / Orazer (see footnote). Orazer (see footnote). Orazer (see footnote).  (For lumes Mechanical General Min. / Orazer (see footnote). Orazer (see footnote).  (For lumes Mechanical Min.	Ventilation	Local Exhaust	Air	flow to produce velocit	y of Special	Natural(min): 10,000 cu.ft	/brazer
Protective Gloves Leather welding gloves.  Eve Protection Plastic frame safety spectacles with side shields-filter lenses shade #3 or #4.  Other Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	(For fume:	Mechanical (C	eperally	./min in brazing zone. min./brazer(see footnot	e) Other	16ft. ceiling no obstructi	ons.
Other Protective Clothing or Equipment Normal clothing for torch brazing. (Avoid flammable fabrics.)	Protective Glove	S Leather 4	ieldi	ng gloves.	ye Protection P	lastic frame safety spects	cles with
	Other Protective	Clothing or Equi	nmant				_
	Work/Hygienic F	Practices	,	MOTHER CTOPITUE LOL. COL.	OH DLASTIF	Z. TAVOTO ITAIINADIS ISBITO	~~ ·